

# Christopher Radbill's Automotive Repair

# REPAIR ORDER

906 Old Fernhill Road, Unit 6  
 West Chester, PA 19380  
 610-701-9401

DATE	R.O. #
11/29/2006	6509

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8232	Porsche	912	1966		51,386
QUANTITY	DESCRIPTION			RATE	AMOUNT
11.5	Labor			85.00	977.50T
	Change oil and filter				0.00T
	Rebuild front brake calipers.				0.00T
	Bleed brake fluid .				
	Replace front brake pads.				
	Troubleshoot and diagnose - Passenger seat recline function inoperative				0.00T
	Remove passenger seat to disassemble, clean, and repair recliner mechanism.				0.00T
	Not possible to install front tow hooks. Hooks are for a later car.				0.00T
	Troubleshoot and diagnose - Car pulls slightly to the right.				0.00T
	We will address this after new tires are installed.				0.00T
	Repair washer pump tubing and aim washer jets.			85.00	85.00T
	Subtotal - Labor				1,062.50
	Oil filter			18.96	18.96T
	Subtotal - Parts				18.96
6	1 Quart Oil			3.26	19.56T
	Subtotal gas,oil,grease				19.56
	Subtotal				1,101.02
	Sales Tax			6.00%	66.06
We appreciate your business. Please visit our website -RADBILLAUTO.com				<b>Total</b>	\$1,167.08

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.