

Christopher Radbill's Automotive Repair

REPAIR ORDER

906 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

| | |
|-----------|--------|
| DATE | R.O. # |
| 2/20/2008 | 7262 |

| |
|--|
| BILL TO |
| Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914 |

| LICENSE # | MAKE | MODEL | YEAR | SERIAL # | ODOMETER |
|-----------|---------|-------|------|----------|----------|
| EZP 8232 | Porsche | 912 | 1966 | | 56,962 |

| QUANTITY | DESCRIPTION | RATE | AMOUNT |
|----------|--|--------|-----------|
| 20 | Weld front pan. | 85.00 | 1,700.00T |
| 0.8 | Grind rust off gas tank and paint with rust inhibitor. | 85.00 | 68.00T |
| 0.8 | Change oil and filter | 85.00 | 68.00T |
| 2.5 | Replace steering coupler. | 85.00 | 212.50T |
| 2 | Replace hood seal. | 85.00 | 170.00T |
| | Grind rust off front bumper, paint with rust inhibitor, and replace front bumper seal. | 85.00 | 85.00T |
| | Subtotal - Labor | | 2,303.50 |
| | Steering Coupler | 85.66 | 85.66T |
| | Oil filter | 20.24 | 20.24T |
| | Front Pan | 315.00 | 315.00T |
| | Gas tank seal | 10.00 | 10.00T |
| | Subtotal - Parts | | 430.90 |
| | Spray Trim Adhesive | 19.33 | 19.33T |
| 1.5 | Rubberized undercoating | 6.54 | 9.81T |
| | Rust Inhibitor | 8.39 | 8.39T |
| | Primer Spray | 20.00 | 20.00T |
| 0.25 | Sealant | 44.70 | 11.18T |
| 4 | 1 Quart Oil | 3.26 | 13.04T |
| | MOA oil additive | 10.00 | 10.00T |
| | Subtotal - Gas, oil, and grease. | | 91.75 |
| | Subtotal | | 2,826.15 |

Thank you for your business. Please visit our website at RADBILLAUTO.com

Total

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

Christopher Radbill's Automotive Repair

REPAIR ORDER

906 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

| | |
|-----------|--------|
| DATE | R.O. # |
| 2/20/2008 | 7262 |

| |
|--|
| BILL TO |
| Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914 |

| LICENSE # | MAKE | MODEL | YEAR | SERIAL # | ODOMETER |
|-----------|---------|-------|------|----------|----------|
| EZP 8232 | Porsche | 912 | 1966 | | 56,962 |

| QUANTITY | DESCRIPTION | RATE | AMOUNT |
|----------|-------------|-------|--------|
| | Sales Tax | 6.00% | 169.57 |

| | |
|--|-------------------------|
| Thank you for your business. Please visit our website at RADBILLAUTO.com | Total \$2,995.72 |
|--|-------------------------|

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.