

Christopher Radbill's Automotive Repair

SERVICE ESTIMATE

906 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

DATE	R.O. #
9/25/2008	7657

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8232	Porsche	912	1966		57,004

QUANTITY	DESCRIPTION	RATE	AMOUNT
	Perform Pennsylvania State Inspection	22.00	22.00T
	Insp. Specifications. Tires 5/32 Brakes L/F 5/B R/R 7/B Sticker# AI8 - 9725815	0.00	0.00T
	Troubleshoot and diagnose: Car will not start.	0.00	0.00T
0.3	Replace fuel filter	90.00	27.00T
1.5	Replace customer supplied speedo drive	90.00	135.00T
1.8	Install hot start relay kit.	90.00	162.00T
	Subtotal - Labor		346.00
	Relay Kit	67.00	67.00T
	Fuel Filter	2.74	2.74T
	Subtotal - Parts		69.74
	Subtotal		415.74
	Sales Tax	6.00%	24.94

Thank you for your business. Please visit our new website at RADBILLAUTO.com	Total	\$440.68
--	--------------	----------