

Christopher Radbill's Automotive Repair

REPAIR ORDER

906 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

DATE	R.O. #
2/25/2010	8705

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8232	Porsche	912	1966	1.6L	60,822

QUANTITY	DESCRIPTION	RATE	AMOUNT
	Troubleshoot and diagnose: Engine noise - flapping.	0.00	0.00T
6.25	Remove rt. side rocker arm assembly to replace broken #1 cylinder intake valve spring. Straighten bent #1 intake pushrod. Perform complete valve adjustment. Road test and recheck valves - OK	95.00	593.75T
	Replace brake fluid and bleed brake system.	95.00	95.00T
	Change oil and filter	19.50	19.50T
	Subtotal - Labor		708.25
	Oil Filter	13.19	13.19T
	Valve Spring	25.18	25.18T
2	Valve cover gasket	7.59	15.18T
	Subtotal - Parts		53.55
6	1 Quart Oil	4.24	25.44T
	MOA oil additive	10.60	10.60T
	Super Blue Brake Fluid	23.73	23.73T
	Subtotal - Gas, oil, and grease		59.77
	Subtotal		821.57
	Sales Tax	6.00%	49.29

Thank you for your business. Please visit our new website at RADBILLAUTO.com	Total	\$870.86
---	--------------	----------

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.