

Christopher Radbill's Automotive Repair

REPAIR ORDER

909 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

DATE	R.O. #
10/26/2005	5732

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8323	Porsche	912	1966		47,006
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Troubleshoot and diagnose - transmission problem with first gear. The car slips out of first gear with a bang and/or thud. The stick shift lever can be held to prevent slipping out of first gear			0.00	0.00T
26	Remove engine and transmission to disassemble transmission and repair / replace worn / damaged parts as necessary.			80.00	2,080.00T
	Replace front main crankshaft seal				0.00T
	Replace engine compartment sound insulation pad.			0.00	0.00T
	Perform Pennsylvania State Inspection			22.00	22.00T
	Insp. Specifications. Tires 9/32 Brakes L/F 12/B R/R 10/B Sticker# AI5 - 9846108			0.00	0.00T
	Change oil and filter			19.50	19.50T
4.5	Replace 2 vent window seals in doors - \$360.00			0.00	0.00T
	Replace oil pressure switch			0.00	0.00T
	Replace missing bushing for throttle cable/rod pivot on transmission			0.00	0.00T
	Replace throw-out bearing fork guides			0.00	0.00T
0.8	Troubleshoot inop. turnsignal indicator light in tachometer. Replaced incorrect flasher relay.			80.00	64.00T
	Subtotal - Labor				2,185.50
	Turnsignal Relay			58.63	58.63T
Thank you for your business. Please visit our new website at RADBILLAUTO.com				Total	

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

Christopher Radbill's Automotive Repair

REPAIR ORDER

909 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

DATE	R.O. #
10/26/2005	5732

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8323	Porsche	912	1966		47,006

QUANTITY	DESCRIPTION	RATE	AMOUNT
	ST gasket set	83.44	83.44T
	ST Syncro sleeve	577.94	577.94T
	Mainshaft seal	4.50	4.50T
	Oil filter - supplied by customer	0.00	0.00T
2	Vent window seals- supplied by customer	0.00	0.00T
	Mainshaft bearing	167.98	167.98T
	Pinion bearing	167.98	167.98T
	Pinion bearing pinion end	100.00	100.00T
	1st gear thrust shim	30.00	30.00T
	Crankshaft seal	27.65	27.65T
2	Oil pan gasket	4.15	8.30T
	Hood pad	74.69	74.69T
	Oil pressure sender	7.62	7.62T
	Shift rod seal	13.74	13.74T
	Throttle bushing	2.65	2.65T
	Throw-out bearing fork guides	10.00	10.00T
	Subtotal - Parts		1,335.12
4	1 Quart Oil	3.33	13.32T
	MOA oil additive	9.40	9.40T
3.6	Syncro Shift transmission oil.	15.00	54.00T
	Spray trim adhesive	12.00	12.00T
	Subtotal - Gas, Oil, Grease		88.72

Thank you for your business. Please visit our new website at RADBILLAUTO.com	Total
--	--------------

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

Christopher Radbill's Automotive Repair

REPAIR ORDER

909 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

DATE	R.O. #
10/26/2005	5732

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8323	Porsche	912	1966		47,006

QUANTITY	DESCRIPTION	RATE	AMOUNT
	Subtotal		3,609.34
	Sales Tax	6.00%	216.56

Thank you for your business. Please visit our new website at RADBILLAUTO.com	Total \$3,825.90
--	-------------------------

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.