

Christopher Radbill's Automotive Repair

REPAIR ORDER

906 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

DATE	R.O. #
9/12/2007	6974

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8232	Porsche	912	1966		56,124
QUANTITY	DESCRIPTION			RATE	AMOUNT
6	Replace rear wheel bearings			85.00	510.00T
0.8	Change oil and filter			85.00	68.00T
	Replace brake fluid and bleed brake system			85.00	85.00T
	Subtotal labor				663.00
	Oil filter			20.24	20.24T
	Subtotal				20.24
6	1 Quart Oil			3.26	19.56T
	MOA oil additive			10.00	10.00T
	Subtotal gas,oil,grease				29.56
	Subtotal				712.80
	Sales Tax			6.00%	42.77
This is an estimate only. Actual charges may vary.				Total	\$755.57

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.