

Christopher Radbill's Automotive Repair

REPAIR ORDER

906 Old Fernhill Road, Unit 6
 West Chester, PA 19380
 610-701-9401

DATE	R.O. #
9/7/2010	9150

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8232	Porsche	912	1966	1.6L	161,415

QUANTITY	DESCRIPTION	RATE	AMOUNT
	Perform Pennsylvania State Inspection	22.00	22.00T
	Insp. Specifications. Tires 6/32 Brakes L/F 7/B R/R 6/B Sticker# AI0 - 7731816	0.00	0.00T
0.6	Change oil and filter	98.00	58.80T
9	Remove and reinstall trim to wet-sand, polish and wax car to reverse fading and bring out original color.	98.00	882.00T
1.5	Remove distributor to clean, lubricate, and replace burned points.	98.00	147.00T
	Subtotal - Labor		1,109.80
	Paint touch-up.	200.00	200.00T
	Subtotal - Outside Service		200.00
	Wet Sanding Materials	35.00	35.00T
2	Window Washer Nozzles	18.64	37.28T
	Subtotal - Parts		72.28
6	1 Quart Oil	4.24	25.44T
	MOA oil additive	10.60	10.60T
	Subtotal - Gas, oil, and grease		36.04
	Subtotal		1,418.12
	Sales Tax	6.00%	85.09

Thank you for your business. Please visit our new website at
RADBILLAUTO.com

Total \$1,503.21

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.