

# Christopher Radbill's Automotive Repair

# REPAIR ORDER

909 Old Fernhill Road, Unit 6  
 West Chester, PA 19380  
 610-701-9401

DATE	R.O. #
10/18/2004	5003

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8232	Porsche	912	1966	1.6L	45,287
QUANTITY	DESCRIPTION			RATE	AMOUNT
	Perform Pennsylvania State Inspection			22.00	22.00T
	Insp. Specifications. Tires 10/32 Brakes L/F 8/B			0.00	0.00T
	R/R 9/B Sticker# AI4 - 8885396				
6	Tune- up using customer supplied spark plugs, points & condenser, cap & rotor, and valve cover gaskets.			75.00	450.00T
	Clean / remove crumbling engine compartment insulation to eliminate danger of cooling fan and contaminating air filters and carburetors.			0.00	0.00T
	Synchronize and adjust carburetors and install crankcase breather hose to airfilter housing.			0.00	0.00T
	Change oil and filter using customer supplied oil strainer gaskets and oil filter. Repair warped / leaking oil sump plate. Clean out hardened debris from bottom of oil filter housing.			0.00	0.00T
0.2	Troubleshoot and diagnose - Horn and Washers. Replace horn button grommet.			75.00	15.00T
4.5	Inspect and replace front wheel bearings using customer supplied bearings.			75.00	337.50T
Refer new PORSCHE Customer - receive 10% off next labor charge				<b>Total</b>	

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

# Christopher Radbill's Automotive Repair

# REPAIR ORDER

909 Old Fernhill Road, Unit 6  
 West Chester, PA 19380  
 610-701-9401

DATE	R.O. #
10/18/2004	5003

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8232	Porsche	912	1966	1.6L	45,287
QUANTITY	DESCRIPTION			RATE	AMOUNT
4	Customer states inspect brakes for the following concern/s - Master cylinder reservoir hose is leaking. Replace hose and clean-up damaged / rusted area around leak and repaint using rust encapsulater paint. Bleed / flush entire hydraulic system with dot 4 ATE SL fluid.			75.00	300.00T
6	Replace rear torsion bar / spring plate bushings with updated Weltmeister bushings.			75.00	450.00T
0.4	Change transaxle oil to syncroshift.			75.00	30.00T
3	Repair floor in rt. rear passenger compt. to pass insp.			75.00	225.00T
	Subtotal - Labor				1,829.50
2	Air filter			31.52	63.04T
2	Front wheel grease seals			13.69	27.38T
	Oil Cap Seal			3.00	3.00T
2	Inner spring plate bushing			14.98	29.96T
2	Rear outer spring plate			18.98	37.96T
	Oil filler cap gasket			1.28	1.28T
	Crankcase breather hose			4.00	4.00T
	Shipping.			19.00	19.00T
	Subtotal - Parts				185.62
3	1 Quart Oil			2.76	8.28T
Refer new PORSCHE Customer - receive 10% off next labor charge				<b>Total</b>	

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

# Christopher Radbill's Automotive Repair

# REPAIR ORDER

909 Old Fernhill Road, Unit 6  
 West Chester, PA 19380  
 610-701-9401

DATE	R.O. #
10/18/2004	5003

BILL TO
Bill Hance 503 South Ridley Creek Road Media, PA 19063-4223 VIN# - 451914

LICENSE #	MAKE	MODEL	YEAR	SERIAL #	ODOMETER
EZP 8232	Porsche	912	1966	1.6L	45,287
QUANTITY	DESCRIPTION			RATE	AMOUNT
	1 Qt Marvel Mystery Oil			6.00	6.00T
	Weltmeister spring plate bushing lubricant			5.98	5.98T
4	Syncro Shift transmission oil.			14.00	56.00T
	Body Supplies			20.00	20.00T
	Subtotal - Gas, Oil, Grease				96.26
	Subtotal				2,111.38
	Sales Tax			6.00%	126.68
Refer new PORSCHE Customer - receive 10% off next labor charge				<b>Total</b>	\$2,238.06

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LEIN IS HERBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.